


Water Leakage



20180407T165929.jpg 2018-04-07, 4:59 PM



20180407T165929.jpg 2018-04-07, 4:59 PM




PARAMETERS

| | |
|-------------------------|--------------|
| Emissivity | 0.90 |
| Refl. temp. | 22.0 °C |
| Distance | 3.00 m |
| Relative humidity | 50 % |
| Atmospheric temperature | 20.0 °C |
| Transmission | 0.00 |
| IR window temperature | 25.0 °C |
| IR window transmission | 80 % |
| Lat. | N 43° 8.46' |
| Long. | W 80° 15.31' |


Location: Second Floor Hall way& staircase



20180407T170003.jpg 2018-04-07, 4:59 PM



20180407T170003.jpg 2018-04-07, 4:59 PM




PARAMETERS

| | |
|-------------------------|--------------|
| Emissivity | 0.90 |
| Refl. temp. | 22.0 °C |
| Distance | 3.00 m |
| Relative humidity | 50 % |
| Atmospheric temperature | 20.0 °C |
| Transmission | 0.00 |
| IR window temperature | 25.0 °C |
| IR window transmission | 80 % |
| Lat. | N 43° 8.45' |
| Long. | W 80° 15.31' |


Location: west bedroom



20180407T170006.jpg 2018-04-07, 4:59 PM



20180407T170006.jpg 2018-04-07, 4:59 PM




PARAMETERS

| | |
|-------------------------|--------------|
| Emissivity | 0.90 |
| Refl. temp. | 22.0 °C |
| Distance | 3.00 m |
| Relative humidity | 50 % |
| Atmospheric temperature | 20.0 °C |
| Transmission | 0.00 |
| IR window temperature | 25.0 °C |
| IR window transmission | 80 % |
| Lat. | N 43° 8.45' |
| Long. | W 80° 15.31' |


Location: West bedroom



20180407T170108.jpg 2018-04-07, 4:59 PM



20180407T170108.jpg 2018-04-07, 4:59 PM




PARAMETERS

| | |
|-------------------------|--------------|
| Emissivity | 0.90 |
| Refl. temp. | 22.0 °C |
| Distance | 3.00 m |
| Relative humidity | 50 % |
| Atmospheric temperature | 20.0 °C |
| Transmission | 0.00 |
| IR window temperature | 25.0 °C |
| IR window transmission | 80 % |
| Lat. | N 43° 8.45' |
| Long. | W 80° 15.31' |

Location: east bedroom



20180407T170121.jpg 2018-04-07, 4:59 PM



20180407T170121.jpg 2018-04-07, 4:59 PM




PARAMETERS

| | |
|-------------------------|--------------|
| Emissivity | 0.90 |
| Refl. temp. | 22.0 °C |
| Distance | 3.00 m |
| Relative humidity | 50 % |
| Atmospheric temperature | 20.0 °C |
| Transmission | 0.00 |
| IR window temperature | 25.0 °C |
| IR window transmission | 80 % |
| Lat. | N 43° 8.46' |
| Long. | W 80° 15.31' |

Location: bathroom



20180407T170329.jpg 2018-04-07, 4:59 PM



20180407T170329.jpg 2018-04-07, 4:59 PM



PARAMETERS

| | |
|-------------------------|--------------|
| Emissivity | 0.90 |
| Refl. temp. | 22.0 °C |
| Distance | 3.00 m |
| Relative humidity | 50 % |
| Atmospheric temperature | 20.0 °C |
| Transmission | 0.00 |
| IR window temperature | 25.0 °C |
| IR window transmission | 80 % |
| Lat. | N 43° 8.46' |
| Long. | W 80° 15.31' |

Location: second floor addition